

1704Z 11 JAN 64

SECRET

DIRECTOR

[REDACTED]

OPS 1-12

ROUTINE

TCR: 1729Z 11 JAN 64

IN 58305 25X1A

[REDACTED]

[REDACTED]

1. CAMERA 112A WAS USED IN MISSION 6071 FLOWN ON 30 DEC 1963;
PROCESSING WAS ACCOMPLISHED BY [REDACTED]

25X1A

2. ORIGINAL NEGATIVE:

A. THE NEGATIVE APPEARED SLIGHTLY UNDEREXPOSED. THE RESOLUTION IS GOOD. A MINUS DENSITY STREAK, APPROXIMATELY 0.2" WIDE, OCCURS ON EACH FRAME OF THE LAST TWO THIRDS OF THE FILM, BECOMING PROGRESSIVELY WORSE TOWARD THE END OF THE MISSION. THIS STREAK IS 0.1" FROM THE TITLED, PORT EDGE AND 0.25" FROM THE TITLED, STARBOARD EDGE OF THE FORMAT AREA ON EACH FRAME. THE IMAGERY IS SLIGHTLY DEGRADED IN THE STREAK. THIS STREAK APPEARS TO SPLIT INTO TWO PARALLEL MINUS DENSITY STREAKS FOR APPROXIMATELY THE LAST ONE THIRD OF THE MISSION. AN AREA OF SLIGHT BANDING OCCURS ON EVERY FRAME THROUGHOUT THIS MISSION. THIS AREA EXTENDS 4" TO 5" INTO THE FORMAT FROM THE PORT EDGE OF THE FRAME AND ACROSS THE FORMAT. CONTINUOUS, HEAVY EDGE FOG OCCURS ALONG BOTH EDGES OF THE FILM FOR APPROXIMATELY THE FIRST ONE THIRD OF THE MISSION.

SECRET

25X1A

(IN 58300)

S E C R E T

PAGE TWO

IT THEN BECOMES LIGHT AND INTERMITTENT THROUGH THE END OF THE MISSION WITH THE HEAVIEST FOGGING ALONG THE UNTITLED EDGE OF THE FILM. A STAIN IS PRESENT BETWEEN FRAMES 1895/1896 AND ON FRAMES 1896 AND 1897. MANUFACTURER'S SPLICES ARE NOTED THROUGH FRAMES 315 AND 1762. THE TAKE ARRIVED AT THE PROCESSING SITE IN FOUR SEPARATE SPOOLS. THIS DIVISION CAUSED A SMALL PORTION OF FRAMES 492, 1156, AND 1898 TO BE DAMAGED AS A RESULT OF THE CUT AND SPLICE MADE. FIVE SHORT SCRATCHES OCCUR OUTSIDE THE FORMAT AND NEAR EACH METERING SPACE ALONG THE LEADING EDGE OF THE FILM. A SINGLE SHORT SCRATCH APPEARS ALONG THE TITLED EDGE OPPOSITE THE ABOVE MENTIONED SHORT SCRATCHES.

B. THERE WERE NO MAJOR CAMERA MALFUNCTIONS OR PROCESSING PROBLEMS ENCOUNTERED DURING THE MISSION. THERE ARE 2642 TITLED FRAMES ON THIS MISSION. FRAME 2642 IS A HALF FRAME AND IS HEAVILY FOGGED.

3. POSITIVE:

- A. FI SUITABILITY IS GOOD.
- B. PRINTING AND PROCESSING ARE GOOD.
- C. CLOUDS OBSCURE APPROXIMATELY 20 PERCENT OF THE MISSION.

END OF MESSAGE

S E C R E T